	Fuse Location	Fuse Size	Fast or Slow	Fuse Size	Part Number	Fuse Goes to
Horton						
4160	x	1.25 amp breaker	x	x	C4110	Main
4160-1	x	1.25 amp breaker	x	x	C4110	Main
7160-3	x	3 amp		2AG		
	x	0.8 amp breaker	x	x	C9110	
4190	F1	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Main
	F2	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Motor
	F3	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Control
2160	x	1.5 amp breaker	x	x	C2110	Main
2160-1	x	1.5 amp breaker	x	x	C2110	Main
2160-2	x	1.5 amp breaker	x	x	C2110	Main
2160-4	x	2 amp breaker	x	x	C7261-1	Main
2150	F1	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Main
	F2	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Motor
	F3	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Control
8160-3	x	3 amp				
6150	F1					
	F2					
Besam						
Swingmaster	F1,5A	1.5 amp	Fast	AGC 1-1/4"x1/4"		Control
	F7A	7 amp	Slow	AGC 1-1/4"x1/4"		Main
	Tower			AGC 1-1/4"x1/4"		Motor
Powerswing	F1	6.3 amp		5 x 20mm		
	F2	250 mamp		5 x 20mm		
SW100		6.3 amp	Slow			
Swingmaster 900	x	breaker	x	x	x	Main
Econoswing				AGC 1-1/4"x1/4"		
Freedom	x	1.5 amp		AGC 1-1/4"x1/4"		Main
Electra	F1	4 amp		AGC 1-1/4"x1/4"		
	F2	1 amp		AGC 1-1/4"x1/4"		
CUP	F1	2 amp	Slow	5 x 20mm or AGC		
	F2	10 amp	Slow	5 x 20mm or AGC		
A Series						
B Series						
C Series	F1	4 amp	Slow	AGC 1-1/4"x1/4"		Main
	F2	1.5 amp	Slow	AGC 1-1/4"x1/4"		Control
D Series	F1	10 amp	Slow	AGC 1-1/4"x1/4"		Motor
	F2	2.5 amp	Slow	AGC 1-1/4"x1/4"		Control
CUD 9	F1	5 amp	Fast	AGC 1-1/4"x1/4"		Motor
	F2	2 amp	Fast	AGC 1-1/4"x1/4"		Control
Unislide						
Stanley						
Dynaglide	x	breaker	x	x	x	Main
Model J	F1	3 amp	Fast	AGC 1-1/4"x1/4"	FUSE-3AFA	Main
MC521	x	5 amp	Fast	5 x 20mm	FUSE-5AFA	Main
Magicswing L Shape	x	breaker	x	x	x	Main
Magicswing	x	3 amp	Fast	AGC 1-1/4"x1/4"		Main
D-4990						Main
Magicaccess Single	F1	3 amp	Fast	AGC 1-1/4"x1/4"		Main
Magicaccess Dual		1.5 amp	Slow	AGC 1-1/4"x1/4"		Main

DOM						
Astroswing	x	3 amp		AGC 1-1/4"x1/4"		Main
Astro In Line Fuse	x	0.75 amp		AGC 1-1/4"x1/4"		Motor
Astroslide	x	1.5 map breaker	x	x	4204102971	Main
96K Analog Control	x	6.3 amp		AGC 1-1/4"x1/4"		Control
96K Analog Pwr Sup	x	2 amp		AGC 1-1/4"x1/4"		
	x	2.5 amp		AGC 1-1/4"x1/4"		
96K Digital	F1					
	F2					
Benchmark	x	1.5				
LCN Sr Swing						
Dorma						
ED700 Old	F1	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Main
	F2	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Motor
	F3	3.15 amp	Slow	5 x 20mm	FUSE-3.15ATD	Control
ED700 New	F1	2 amp	Fast	5 x 20mm		
	F2	4 amp	Fast	5 x 20mm		
ED800	x	3 amp	Fast	AGC 1-1/4"x1/4"		
ED400	F1	2 amp	Fast	5 x 20mm		
	F2	4 amp	Fast	5 x 20mm		
EDA	F1	2 amp	Fast	AGC 1-1/4"x1/4"		
ESA						
ESA II		10 amp				
GilDor						
SLM Slider						
FDC Swinger						
GT						
Whisperslide		2 amp	Fast	AGC 1-1/4"x1/4"		
1175 U01 to U03		4 amp	Fast	5 x 20mm		
1175 U03 to U19		5 amp	Fast	5 x 20mm		
300	x					
Magnum	F1					
	F2	3 amp	Fast	AGC 1-1/4"x1/4"		
Gemini						
KM - Record						
B Control						
L Control	x	2 amp	Slow	AGC 1-1/4"x1/4"		
D Control						
K Control	F1	3 amp	Fast	AGC 1-1/4"x1/4"		
	F2	3 amp	Fast	AGC 1-1/4"x1/4"		
	F3	1 amp	Fast	AGC 1-1/4"x1/4"		
3100	F1	3 amp	Fast	AGA		
	F2	2 amp	Fast	AGC 1-1/4"x1/4"		
3500 Single	x	3 amp	Slow	AGC 1-1/4"x1/4"		
3500 Dual	x	3 amp	Slow	AGC 1-1/4"x1/4"		
1100						
Z II						
5100						
6100		2 amp		5 x 20mm		
8100		2 amp		5 x 20mm		

Norton						
5700						
5900		6.3 amp	Slow			
6600						
6900	F1	1.5 amp	Slow	2AG		
Tormax						
TDA - TCP52						
TCP51						
TN 220	x	2 amp		AGC 1-1/4"x1/4"		
TN 120 I Motion						
I Motion Slide	x	5 amp	Slow	AGC 1-1/4"x1/4"		
I Motion Swing	x	5 amp	Slow	AGC 1-1/4"x1/4"		
TTX	F1	1.6 amp				
TTX II	x	5 amp	Slow			